STATUS REPORT

Amelia Cornelius Culture Park

CDC #21-106 Amelia Cornelius Culture Park - Property Repairs

Project Description:
To correspond with the park's Site Amenities project, this proposed project will repair existing structures/ features at the park to address damage from age and use. The proposed repairs include: Dam repairs/ improvements, storm water drainage, site lighting, and addressing miscellaneous site safety deficiencies.

Current Status

- Current plans include a new Asphalt Trail and work around the shoreline including re-work of boat landing, and Riprap frontage as well.
- Coffer Dam being installed 10/7/26 to provide access for camera of Intake and Outflow culverts.
- Both Inlet and Outlet culvert pipe have had fiberglass liner pipe installed.
- Subsurface Inc. injected 52 gallons of U 4.0 Polyurethane Chemical Grout Fill into the top slab around the riser structure. It did what we wanted it to do and that was to push the water in those voids out, and to secure the slab. Eliminating leaks.
- Brown County added breaker run rock and grass matting to runoff area by outlet pipe.

Schedule:
Approvals - 2023
Design - 2025-2026
Consrtuction2026-2027



STATUS REPORT

Amelia Cornelius Culture Park

CDC #21-106 Amelia Cornelius Culture Park - Property Repairs

Project Description:

To correspond with the park's Site Amenities project, this proposed project will repair existing structures/ features at the park to address damage from age and use. The proposed repairs include: Dam repairs/ improvements, storm water drainage, site lighting, and addressing miscellaneous site safety deficiencies.

Current Status

- Current plans include a new Asphalt Trail and work around the shoreline including re-work of boat landing, and Riprap frontage as well.
- Coffer Dam being installed 10/7/26 to provide access for camera of Intake and Outflow culverts.
- Both Inlet and Outlet culvert pipe have had fiberglass liner pipe installed.
- Subsurface Inc. injected 52 gallons of U 4.0 Polyurethane Chemical Grout Fill into the top slab around the riser structure. It did what we wanted it to do and that was to push the water in those voids out, and to secure the slab. Eliminating leaks.
- Brown County added breaker run rock and grass matting to runoff area by outlet pipe.

Schedule:

Approvals - 2023
Design - 2025-2026
Consrtuction2026-2027

